






Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb
/ Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu



Pos.	Part No.
1	A 861 545 AA
2	A 861 371 NU
3	A 861 373 NU
4	A 861 245 NU*
5	A 861 546 NU
6	A 861 372 NU
7	A 861 547 AA
8	A 861 815 AA



CERATHERM C100 A 7533 ..








Ideal Standard

0724 / A 868 968
Made in Germany



Ideal Standard International NV
Corporate Village – Gent Building
Da Vincilaan 2
1935 Zaventem
Belgium
<https://www.idealstandard.com>





	P	bar		MAX. 10		5			Q (3 bar)
	T	°C		MAX. 80		65			I/min
						55			22